

SACHS - 900058 - SERVICE-KIT 2 UDS.RENAULT CLIO I/II

REF.900 058 SACHS

Información de la pieza

Juego de guardapolvos, amortiguador Service Kit

Código de b.:

4013872374663

RENAULT :

CLIO I (B/C57_, 5/357_) Información

- 1.1 (34 kW ; 01/1991 - 09/1998)
- 1.2 (B/C57R) (40 kW ; 01/1991 - 06/1996)
- 1.2 (5/357Y, 5/357K) (40 kW ; 01/1996 - 09/1998)
- 1.2 (B/C/S577) (40 kW ; 01/1996 - 12/1996)
- 1.2 (5/357Y, 5/357K) (43 kW ; 01/1996 - 09/1998)
- 1.2 (B/C/S57A, B/C57S, 5/357F, 5/357J, 5/357L, 5/357R) (43 kW ; 05/1990 - 09/1998)
- 1.2 (B/C/S572) (44 kW ; 05/1990 - 03/1996)
- 1.4 (B57J, C57J) (55 kW ; 01/1991 - 09/1998)
- 1.4 (59 kW ; 01/1991 - 09/1998)
- 1.7 (B/C574) (68 kW ; 01/1991 - 12/1993)
- 1.8 (B/C57C, B/C57U) (65 kW ; 01/1991 - 09/1998)
- 1.8 (B/C578) (66 kW ; 08/1994 - 09/1998)
- 1.8 (70 kW ; 01/1991 - 09/1998)
- 1.8 Rsi (B/C57H) (79 kW ; 08/1995 - 09/1998)
- 1.8 Rsi (B/C579) (80 kW ; 01/1993 - 08/1995)
- 1.8 16V (C57D) (99 kW ; 01/1991 - 03/1996)
- 1.9 D (40 kW ; 01/1997 - 09/1998)
- 1.9 D (B/C/S576, B/C/S57L) (47 kW ; 01/1991 - 09/1998)

CLIO II (BB0/1/2_, CB0/1/2_) Información

- 1.2 (BB0A, BB0F, BB10, BB1K, BB28, BB2D, BB2H, CB0A...) (43 kW ; 09/1998 -)
- 1.2 (BB0A, CB0A) (44 kW ; 03/1999 - 05/2001)
- 1.2 16V (BB05, BB0W, BB11, BB27, BB2T, BB2U, BB2V, CB05...) (55 kW ; 06/2001 -)
- 1.2 (55 kW ; 06/2001 -)
- 1.4 (B/CB0C) (55 kW ; 09/1998 - 05/2005)
- 1.4 16V (B/CB0L) (70 kW ; 10/1999 - 09/2004)
- 1.4 16V (B/CB0P) (72 kW ; 08/2000 -)
- 1.6 (B/CB0D) (66 kW ; 09/1998 - 05/2005)
- 1.6 16V (BB01, BB0H, BB0T, BB14, BB1D, BB1R, BB2KL...) (79 kW ; 09/1998 -)
- 1.5 dCi (B/CB07) (48 kW ; 06/2001 -)

1.5 dCi (B/CB08) (60 kW ; 06/2001 -)
1.5 dCi (74 kW ; 01/2004 -)
1.9 D (B/CB0E) (47 kW ; 09/1998 - 05/2005)
1.9 dTi (B/CB0U) (59 kW ; 12/1999 - 05/2005)

CLIO II Furgón (SB0/1/2_) Información

1.1 (SB0A, SB0F, SB1K, SB2D) (43 kW ; 09/1998 -)
1.2 (SB0A, SB0F, SB10) (44 kW ; 03/1999 - 10/2003)
1.5 dCi (SB07) (48 kW ; 06/2001 -)
1.5 dCi (59 kW ; 06/2001 - 10/2004)
1.5 dCi (60 kW ; 11/2003 -)
1.9 D (SB0E) (47 kW ; 09/1998 -)
1.9 D (SB0J) (48 kW ; 02/2000 - 05/2001)
1.9 DTi (SB0U) (59 kW ; 02/2000 - 05/2001)

KANGOO (KC0/1_) Información

1.2 (KC0A, KC0K, KC0F, KC01) (43 kW ; 08/1997 -)
1.2 16V (KC05, KC06, KC03, KC0T, KC0W, KC1D) (55 kW ; 06/2001 -)
1.4 (KC0C, KC0H, KC0B, KC0M) (55 kW ; 08/1997 -)
1.6 16V (70 kW ; 06/2001 -)
1.5 dCi (42 kW ; 07/2003 -)
1.5 dCi (KC07) (48 kW ; 12/2001 -)
1.5 dCi (50 kW ; 06/2005 -)
1.5 dCi (KC08, KC09) (60 kW ; 07/2002 -)
1.5 dCi (62 kW ; 06/2005 -)
D 55 1.9 (KC0D) (40 kW ; 08/1997 -)
D 65 1.9 (KC0E, KC02, KC0J, KC0N) (47 kW ; 08/1997 -)
1.9 dTi (KC0U) (59 kW ; 02/2000 -)

KANGOO (FC0_) Información

1.2 (FC01, FC0A, FC0F) (43 kW ; 08/1997 -)
1.2 (FC1A) (44 kW ; 07/1998 - 07/2001)
1.2 16V (FC05) (55 kW ; 10/2001 -)
1.4 (FC0C, FC0B, FC0H, FC0M) (55 kW ; 08/1997 -)
1.6 16V bivalent (60 kW ; 06/2005 -)
1.6 16V (70 kW ; 10/2001 -)
1.6 16V 4x4 (FC0L, FC0P, FC0S) (70 kW ; 10/2001 -)
1.5 dCi (FC1R) (42 kW ; 12/2002 -)
1.5 dCi (45 kW ; 10/2005 -)
1.5 dCi (FC07, FC1R) (48 kW ; 12/2001 -)
1.5 dCi (FC1E) (50 kW ; 06/2005 -)
1.5 dCi (FC08, FC09) (60 kW ; 04/2003 -)
1.5 dCi (FC1G) (62 kW ; 06/2005 -)
D 55 1.9 (FC0D) (40 kW ; 08/1997 -)
D 65 1.9 (FC0E, FC02, FC0J, FC0N) (47 kW ; 08/1997 -)
1.9 D (FC0J) (48 kW ; 09/1999 - 06/2003)
1.9 dTi (FC0U) (59 kW ; 09/1998 - 02/2000)
1.9 dTi (FC0U) (59 kW ; 02/2000 -)

1.9 dCi 4x4 (FC0V) (59 kW ; 10/2001 -)
1.9 dCi (FC0V) (62 kW ; 07/2003 -)
1.9 dCi 4x4 (FC0V) (62 kW ; 07/2003 -)

TWINGO I (C06_) Información

1.2 (C067) (40 kW ; 05/1996 -)
1.2 (C063, C064) (40 kW ; 03/1993 - 10/1996)
1.2 (C066, C068) (43 kW ; 05/1996 -)
1.2 16V (C060) (44 kW ; 08/2004 - 06/2007)
1.2 16V (C06C, C06D, C06K) (55 kW ; 01/2001 -)

TWINGO II (CN0_) Información

1.2 (CN0D) (43 kW ; 03/2007 -)
1.2 16V (CN04, CN0A, CN0B) (55 kW ; 03/2007 -)
1.2 16V (CN0K, CN0V) (56 kW ; 03/2007 -)
1.2 Turbo (CN0C, CN0F) (74 kW ; 03/2007 -)
1.5 dCi (CN0E) (47 kW ; 03/2007 -)
1.5 dCi (CN0U) (62 kW ; 04/2008 -)

